

Fig. 1




Fig. 3




Fig. 5






Fig. 6

Fig. 4 (12b)

12b Fig. 2 '66



[illegible]

Fig. 9




Fig. 10




Fig. 11




Fig. 13




Fig. 12A




Fig. 12B




Fig. 16




Fig. 14




Fig. 15

FIG. 17




Fig. 17




Fig. 19





Fig. 18

Fig. 20

Fig. 21












Fig. 24

FIG. 20



107/112






Fig. 33




Fig. 34




Fig. 37




Fig. 36

AS 106 1310
2 14 2001




Fig. 35




Fig. 38




Fig. 39

SECTION B-B




Fig. 42

SECTION A-A




Fig. 47

SECTION F-F




Fig. 40




Fig. 41




Fig. 44






Fig. 43



cut at middle of clutch's teeth

SECTION C-C

Fig. 45



cut at bottom of clutch's teeth

SECTION E-E

Fig. 46




Fig. 49




Fig. 48




Fig. 50




Fig. 53




Fig. 52




Fig. 51




Fig. 56




Fig. 55




Fig. 54




Fig. 57

SECTION B-B




Fig. 58




Fig. 59




Fig. 60




Fig. 61




Fig. 62




Fig. 63




Fig. 64




Fig. 65




Fig. 66




Fig. 67




Fig. 68




Fig. 73




Fig. 74




Fig. 69




Fig. 70




Fig. 71







Fig. 72

FIG. 75






Fig. 78




Fig. 79

FIG. 80





Fig. 80





Fig. 81

FIG. 82





Fig. 83




Fig. 86




Fig. 84




Fig. 85




Fig. 87




Fig. 88




FIG. 89




FIG. 90







Fig. 93




Fig. 96




Fig. 95